

**CORRECTIONS STANDARDS AUTHORITY  
CORRECTIONS PLANNING AND PROGRAMS DIVISION  
YOUTH CENTERS/YOUTH SHELTERS PROGRAM  
MONITORING REPORT**

**Project Name:** El Centro Youth Center

**Contract Number:** 91-184

**Agency Name:** City of El Centro

**Youth Center** ☒ **Youth Shelter** ☐

**Facility Address:** 750 Park Avenue,  
El Centro CA92243

**Monitoring Term:** 10 years ☐ 20 years ☒

**Facility Phone:** (760) 337-4570

**Date Monitoring Term Ends:** 5/17/2015

**Date of Monitoring Visit:** June 3, 2008

**Field Representative:** Aaron Long

**Person(s) interviewed during the Monitoring Visit (Name, Title, Agency):**

Kristie Riester, Director, Parks & Recreation, City of El Centro

**Brief Project Description:** The project encompassed the construction of a recreation building with a full size gymnasium, activity rooms, counseling room, and offices for recreation staff. The facility is on city owned land and was constructed next to the city's public pool.

**A. SITE REVIEW**

1. Is the facility being used as described in the contract? ☒ Yes ☐ No
2. Is the facility in satisfactory condition and being maintained properly? ☒ Yes ☐ No  
Facility is very well maintained.

**B. PROGRAM REVIEW**

1. What types of programs/services does the facility offer? If available, attach a schedule of activities.  
The programming includes: youth sports leagues, summer day camp, tutoring, nutrition program, and a summer lunch program.
2. Are the programs/services provided by the facility consistent with the contract? ☒ Yes ☐ No
3. Have there been any significant changes to programming? ☐ Yes ☒ No

4. Does the facility have an established process for receiving and considering feedback and suggestions from the community? ☒ Yes ☐ No  
The City conducts periodic evaluations and solicits community involvement.
5. What is the average daily attendance?  
The average monthly attendance exceeds 4,800.
6. What is the maximum capacity?  
450

### C. MONITORING SUMMARY

1. Is the project in compliance with the contract requirements? ☒ Yes ☐ No  
If no, is a Corrective Action Plan needed? ☐ Yes ☐ No
2. Does the project have any technical assistance needs? ☐ Yes ☒ No
3. General Comments/Observations  
The facility is very well maintained and in excellent condition despite over a decade of use. The facility maintains attendance records that demonstrate a high level of use. During the monitoring visit, part of the facility was being used as a polling place.

CSA Field Representative

\_\_\_\_\_  
Aaron Long

Reviewed by:

\_\_\_\_\_  
Marlon Yarber, Deputy Director  
Corrections Planning and Programs Division

Date Reviewed:

\_\_\_\_\_